

MURPHY HOUSE PROJECT PLAYGROUND SAFETY REPORT CARD

CONDITION of equipment: PASS

There are no broken or missing components or damaged structure, no peeling paint, and the swing set is not made of heavy material like metal.

SURFACES must be smooth: PASS

There are no rough or ragged surfaces, sharp points or splinters, or protruding nails, or hooks; all nuts are covered with smooth bolts.

TRIP hazards eliminated: PASS


There are no objects that could be tripped over, no exposed footing, anchoring on environmental obstacles

TIPPING of equipment prevented: PASS

All equipment is properly secured, and there are no loose or movable foundations.

FALL ZONES adequate: PASS

The surface material extends at least 6 feet on all sides, and approximately twice the height of the swings on the front and back



GAPS or SPACES absent: PASS

No apparent gaps/spaces where children could get caught. S-Hook are swings are closed tightly (a credit card or penny cannot fit through the gap.)



ELECTRICAL WIRES secured: PASS

No exposed electrical wires

No DANGEROUS TREES: PASS

There are no trees within a 25 foot radius of the playground.

SURFACE AREAS safe and uniform: PASS

Surface area is uniform 3-inch layer of rubber mulch, which is the required depth for this particular rubber mulch.

HAZARDS REMOVED: PASS

There are no swinging trapeze bars, monkey bars, exercise rings, or trampolines. The climbing rope is secured at both ends to the ground.

